

## IMC Potash, Esterhazy MCC Room Roof Repairs

STRUCTURE: Electrical MCC Room  
 LOCATION: K-2 Minesite, Esterhazy  
 PROJECT DATE: 2002 & 2003  
 JOB DURATION: 4 Weeks per Year  
 CLIENT CONTACT: Terry Heal  
 CONTRACT AREA: 6,000 ft<sup>2</sup>  
 CONTRACTOR: Vector Construction Ltd.  
 Saskatchewan Branch



### PROJECT DESCRIPTION:

Problem: Wash-down water leaking through the roof & dripping down onto electrical control equipment.

Recommended Repair System: Qualipur Traffic Bearing Polyurethane Membrane System.

- Procedure:
- Remove existing deteriorated membrane system, originally installed 18 years ago.
  - Patch and repair concrete substrate as required.
  - Rout and seal all cracks and expansion joints using Sonneborn NP1.
  - Properly prepare and install Qualipur traffic bearing membrane, seed the top coat to saturation with Unimin Round Sand of proper gradation.



#### CORPORATE OFFICE

474 Dovercourt Drive  
 Winnipeg, Manitoba, R3Y 1G4  
 Ph. (204) 489-6300  
 Fax (204) 489-6033  
 Email: vector@vectorgroup.com

#### REGIONAL OFFICES

Manitoba Winnipeg (204) 489-6300  
 Ontario (North) Thunder Bay (807) 346-4405  
 Ontario (South) Stoney Creek (905) 662-4020  
 Saskatchewan Saskatoon (306) 934-3533  
 Alberta Spruce Grove (780) 962-6778

North Dakota Fargo (701) 280-9697  
 Nebraska Sioux City (402) 494-9305  
 Iowa Cedar Rapids (319) 364-5355

#15-02SK\_IMC Esterhazy