

United Grain Growers Leg Pit Repairs Thunder Bay, Ontario

LOCATION:

Thunder Bay, Ontario

PROJECT DATE:

July, 2001

PRODUCT USED:

3M 5600 Urethane
ThoRoc SP20

JOB DURATION:

1 Day

CLIENT:

United Grain Growers

AREA:

Leg Pits

PROJECT DESCRIPTION:

Vector was hired to repair the water leaks in the leg pits. The leaks were caused by cracks in the concrete and that the pits are approximately 10 feet below the surface of the lake. Holes were drilled along the crack and ports installed then 3M 5600 was injected through the ports into the crack to stop the leaks.

**CORPORATE OFFICE**

474 Dovercourt Drive
Winnipeg, Manitoba, R3Y 1G4
Ph. (204) 489-6300
Fax (204) 489-6033
Email: vector@vectorgroup.com

REGIONAL OFFICES

Manitoba Winnipeg (204) 489-6300
Ontario (North) Thunder Bay (807) 346-4405
Ontario (South) Stoney Creek (905) 662-4020
Saskatchewan Saskatoon (306) 934-3533
Alberta Spruce Grove (780) 962-6778

North Dakota Fargo (701) 280-9697
Nebraska Sioux City (402) 494-9305
Iowa Cedar Rapids (319) 364-5355